# Office of the Monroe County Surveyor

Trohn Enright-Randolph



Health Services Building 119 West 7<sup>th</sup> Street Bloomington, IN 47404 Phone: (812) 349-2570 surveyorsoffice@co.monroe.in.us

## AGENDA SURVEYOR REVIEW BOARD REGULAR MEETING Via Zoom App Tuesday, June 21, 2022

- I. Call to Order
- II. Approval of agenda
- III. Approval of meeting minutes from April 19, 2022
- IV. New Business
  - a. Office Update
  - b. Review of 0076\_Deckard Land Surveying Corner Perpetuation Surveys:
    - i. T09N-R02W-15\_2022\_MCR\_Deckard\_2022007082.IN\_RSID004805
    - ii. T09N-R02W-16\_2022\_MCR\_Deckard\_2022007083.IN\_RSID004804
    - iii. T09N-R02W-21\_2022\_MCR\_Deckard\_2022007088.IN\_RSID004803
    - iv. T09N-R02W-22\_2022\_MCR\_Deckard\_2022007089.IN\_RSID004802
- V. Certification of corners: VanBu\_U19, Rich\_S13
- VI. Public input
- VII. Adoption of next meeting date
- VIII. Adjournment

Zoom Meeting Information <u>https://monroecounty-</u> <u>in.zoom.us/j/84648553923?pwd=VmdvUGI1MFR5NzU3VmhXK1JiejZzUT09</u> Meeting ID: 846 4855 3923 Password: 668366 **Dial by your location** +1 312 626 6799 US (Chicago) Meeting ID: 846 4855 3923

#### The meeting is open to the public. Dates are subject to change.

For additional information, please call the Office of the Monroe County Surveyor at (812) 349-2570.

Anyone who requires an auxiliary aid or service for effective communication, or a modification of policies or procedures to participate in a program, service, or activity of Monroe County, should contact Monroe County Title VI Coordinator, (812) 349-2553, as soon as possible but no later than forty-eight (48) hours before the scheduled event.

Individuals requiring special language services should, if possible, Government Title VI Coordinator at least seventy-two (72) hours prior to the date on which the services will be needed.

N:\Meetings\_Boards\_Committees\_&\_Commissions\Monroe\_County\_Surveyor\_Review\_Board\SRB2022\Packets\20220621\Individual Files\MCSRB\_Agenda\_20220621.docx Page 1 of 1



## **MINUTES**

## SURVEYOR REVIEW BOARD

## **REGULAR MEETING**

## Hybrid Health Building Meeting Room and via Zoom App

## APRIL 19, 2022 at 4 PM

## MEMBERS PRESENT: Todd Borgman, Eric Deckard, Rachel Oser

## MEMBERS ABSENT: None

**STAFF:** Trohn Enright-Randolph (County Surveyor), Donna Barbrick (Secretary), Jason George (Survey Technician), Technical Services

**I. Call to Order:** Trohn Enright-Randolph called the meeting to order.

## II. Approval of Agenda

Motion to approve by Borgman; second by Oser. VOTE by roll call: Borgman YES, Deckard YES, and Oser YES. Motion carried unanimously.

## **III.** Approval of meeting minutes from February 22, 2022

Motion to approve by Oser; second by Borgman. VOTE: Oser YES, Borgman YES, and Deckard YES. Motion carried unanimously.

## IV. New Business

## a. Office Update

Trohn talked about using the Health Building meeting room for hybrid meetings. He said MCSO has a new part-time field assistant.

## V. Certification of corners:

**Blm G01.** Trohn said the same cap was found and there were new witnesses. Deckard had a question about a distance and a possible shift in the township line.

**Blm I01.** There was a discussion of how the circumference of trees was being measured. Trohn suggested approval of the corner conditional to converting circumference to diameter.

Wash G25. Trohn suggested a motion for approval conditional to re-evaluating measurements of trees, converting circumference to dbh (diameter at breast height).

Wash I25. Measuring by dbh was discussed. Oser had a comment about the triangles on the temp up.

## Trohn suggested a motion to approve Blm G01, Wash G25, Blm I01, Wash I25 conditional to

- re-evaluating references for trees
- correcting Michael Sheppard's PS number
- correcting points on Wash I25 witness #10109 to witness #10112

• checking the bearings/coordinates on Wash I25 and Blm I01.

Motion by Deckard; second by Borgman. Vote: motion carried 3-0. Corners approved with conditions.

## **Public Input – none**

**Adjournment.** The meeting adjourned at approximately 5:21 pm. The next meeting date is scheduled for June 21.

Minutes appro	ed:
Secretary:	
j·	

MCSRB\_Packet




06/19/2022 **MONUMENT RECORD** Corner ID: **VanBu\_U19** 1/4 **Corner** Sections 25, 26 - T08N-R02W, 2nd P.M. VanBuren Township, Monroe County, Indiana

				4	ŀ		
ĪĪ	ecti	⊢ on 2	6	ĪĪ	ecti	on 2	5
-T07N-R02W-			-T07N-R02W-				
Van Buren			Van Buren				

**MONUMENT:** Describe monument set or found (Include material type, scribing, distance above/below grade, dimensions.) 5/8" Rebar with yellow plastic cap stamped "UTT S-0089" found with base of cap at grade, approximately 30' east of Leonard Springs Road.

#### MONUMENT LOCATION SKETCH:





OFFICE OF THE MONROE COUNTY SURVEYOR • Trohn Enright-Randolph 119 W 7th Street, Bloomington, IN 47404 • 812-349-2570 • surveyorsoffice@co.monroe.in.us

Page 1 of 2

MCSRB\_Packet



MONUMENT RECORD Corner ID: VanBu\_U19 ¼ Corner Sections 25, 26 - T08N-R02W, 2nd P.M. VanBuren Township, Monroe County, Indiana

06/19/2022

5					
Section 25					
-T07N-R02W-					
Van Buren					

#### PHOTO IDENTIFIED: Photo Date: 5/23/2022







Photo Orientation & Description: Looking north at VanBu U19

#### ORIGINAL OR SUBSEQUENT SURVEY EVIDENCE FOUND: Include, search area or areas, search procedure, etc.

Date of Field work/Search: 5/23/2022 By: HJ & JG Monument Found: Rebar with Utt cap. BTs or Reference Objects Found: Witnesses B, D, E & F were all found from 2006 monument record. Project #: Van Buren Preservation Field Book: 54/62 Equipment: Coordinate data was collected with a Javad Triumph LS Network Rover. The basis of bearings is Grid North NAD83(2011), Indiana West Zone, Epoch 2010.0000, Geoid Model G2012BU7, Datum NAD83\_NO\_TRANS, US Survey Feet, derived from GPS observations utilizing the Indiana Real-Time Network (INCORS). Distances obtained with GPS have not been adjusted to ground. Coordinates are available upon request. Notes: All witness photos on file in the Monroe County Surveyors Office.

# **OTHER EVIDENCE:** Describe corner location relative to nearby features and how to reach the corner location – note fences, roads, timber cutting lines, mow lines, clearings, plantings, streams, topo changes, etc.

VanBu\_U19 is located approximately 30' off of the east side of Leonard Springs Road, within a thicket where the parcels for 5479, 5667 and 5705 Leonard Springs Road could be found adjacent. The best path to the rebar is to approach it westerly from 5705 Leonard Spring Rd.'s driveway and along their fence line. Both the power line pole, the "Protect Nearby Survey Markers" sign and the railroad tie post can be spotted from road.

#### MONUMENT PRESERVATION: Describe work done to preserve existing monument.

"Protect Nearby Survey Markers" sign was replaced with a new one fastened with conduits. The sign post was painted. All witnesses were tied off with pink tape. A new mag nail with washer was set in power line pole. Clearing of overgrown vegetation aided in monument's visibility and access from the road. Geodetic Coordinates were collected for VanBu\_U19 along with the new witness (#103001).

**THEORY OF LOCATION:** Describe the theory of location for acceptance of this monument. Include monument origin and associated uncertainty. The rebar was previously witnessed by the Monroe County Surveyor, Kevin Enright, on June 29, 2006 and accepted by the Monroe County Surveyor Review Board on October 24, 2006. The 2006 Monument Record accepted the rebar per a preliminary plat by Bernard A. Guerrettaz on file at the Surveyor's Office as RSID004811. References on File: Eric L. Deckard plat, Fowler Revocable Trust Minor Subdivision (2018), on file at the Recorder's Office as 2018014154.IN and Adam Christenberry survey, Location Route Survey for the Monroe County Highway Department Rockport Road Over Clear Creek (2021), on file at the Recorder's Office as 2012016767.IN. Historic research has not yet been performed to prove the validity of this monument.

#### **CERTIFICATION:**



OFFICE OF THE MONROE COUNTY SURVEYOR • Trohn Enright-Randolph 119 W 7th Street, Bloomington, IN 47404 • 812-349-2570 • surveyorsoffice@co.monroe.in.us

Page 2 of 2

#### 06/19/2022

MONUMENT RECORD State of Indiana - County of Monroe

Section: 26

Township: 8 North

Range: 2 West

Corner ID: VanBu U-19

6

Monument Description & Remarks: 5/8" Rebar with, "Utt", cap found. Set metal post on north side with Survey Sign 4.5ft above ground.

References On File: Bernard A. Guerrettaz survey, Fowler Road Subdivision (2006), survey on file in Surveyor Office.

RECOVERY TIE DRAWING Field Book 38 Page No. 24		
		26
B		
	*-	
Loommet Springs R		
A - 5/8" Rebar with cap.		
<b>B</b> - N 86° E 10.01' to MAG nail in 3"x5"x5' Wood Post.		1.
C - S 86° E 5.66' to 1/2" Iron Pipe. D - S 45° E 20.38' to MAG nail		
in 5"x8" R.R. Tie Post.		
E - S 65° W 30.40' to Edge of Road. F - S 62° W 12.32' to MAG nail		
in 11" PWP.	Not To Scale Compass Bearing M	agnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section, 36,24,2,1 of the Indiana Code; and the above data

is given under my hand and seal this 29th day of Long Administered by the Monroe County Surveyor Revent

06 Date: 10



MCSRB Packet

06/19/2022

"In the second

Drawn by: T.E.R Print date: August 14, 2006

MCSRB\_Packet 06/19/2022

MONUMENT RECORD
Corner ID: Rich\_S13
Quarter Corner
Sections 14 & 23-T09N-R02W, 2nd P.M.
Richland Township, Monroe County, Indiana

**MONUMENT:** Describe monument set or found (Include material type, scribing, distance above/below grade, dimensions.) 1 ¼" Iron Pipe 0.3' above grade at southwest corner of Westbrook Downs Section 4 Part 3.

#### MONUMENT LOCATION SKETCH:



WITNESS MONUMENT TIES

All ties to new Bearing Trees (BTs) are a mag nail set in a 1-1/2" plastic washer stamped "SURVEY MARKER - DO NOT REMOVE" and hack mark at the root crown (less than 12" above ground) perpendicular to the center of the tree, unless otherwise noted. BT diameters are noted as dbh and are measured approximately 4.5' above ground. Bearings are measured from the monument to the center of the BT, distances are measured from the monument to the mag nail.

ID	BEARING	DISTANCE	DESCRIPTION	
Witness A	N 1d E	6.8'	Mag nail with washer set in hack 0.4' above grade on the east side of a 3" oak tree	
Witness B	N 78d E	5.6'	Center top of 2.75' tall Cable Tower as per 2006 monument record.	
Witness C	S 56d E	18.1'	Found Mag Nail on "Protect Nearby Survey Marker" sign 5' above grade as per 2006 monument record.	
MONUMENT ACCESSORIES				
Other survey grade monuments that were located in the vicinity and their relation to the monument. Geodetic coordinates in this table are provided in the format Easting, Northing.				
(#103023)	N 88d57'33" E	29.98'	5/8" Rebar 0.3' above grade as per Witness C of 2006 monument record. This is the presumed southeast corner of Lot 53 as per plat for Westbrook Downs Section 4 Part 3.	



OFFICE OF THE MONROE COUNTY SURVEYOR • Trohn Enright-Randolph 119 W 7th Street, Bloomington, IN 47404 • 812-349-2570 • surveyorsoffice@co.monroe.in.us

Page 1 of 2

MCSRB\_Packet



06/19/2022

## MONUMENT RECORD Corner ID: Rich\_S13 Quarter Corner Sections 14 & 23-T09N-R02W, 2nd P.M. Richland Township, Monroe County, Indiana

_ (	5	
	Section 14 09N-R02W- <i>Richland</i>	
-	Section 23 09N-R02W	
	i I i	

#### PHOTO IDENTIFIED: Photo Date: 04/18/2022





Photo Orientation & Description: Looking west at Rich\_S13

#### · \_

Photo Orientation & Description: Rich S13 from above

ORIGINAL OR SUBSEQUENT SURVEY EVIDENCE FOUND: Include, search area or areas, search procedure, etc.

Date of Field work/Search: 04/18/2022 By: JG & HJ Monument Found: Iron Pipe BTs or Reference Objects Found: Found Witnesses B, C & D from 2006 Monument Record Project #: Rich\_S13 Field Book: 54/53 Equipment: The basis of bearings is Grid North System NAD83(2011)/Indiana West NAVD 88, Epoch 2010.0000, geoid12b\_conus.db3, US Survey Feet, derived from GPS observations utilizing the Indiana Real-Time Network (INCORS). Coordinate data was collected with a Javad Triumph LS Network Rover. Coordinates are available upon request. Distances to witness ties were collected with a Leica Disto laser distance meter. Bearings to witness ties were collected with the internal magnetic compass of the Javad Triumph LS and were automatically adjusted to grid north and are approximately shown hereon for reference. Priority should be given to provided distances over bearings. Notes: All witness photos on file in the Monroe County Surveyors Office.

**OTHER EVIDENCE:** Describe corner location relative to nearby features and how to reach the corner location – note fences, roads, timber cutting lines, mow lines, clearings, plantings, streams, topo changes, etc.

Rich\_S13 is located at the southwest corner of Westbrook Downs Section 4 Part 3 and at the northwest corner of a residence for 5060 N Aldrin Court.

#### MONUMENT PRESERVATION: Describe work done to preserve existing monument.

Geodetic controls were captured for the monument as well as for (#103023) rebar. Sign was on utility pole. Set a new with witness A.

**THEORY OF LOCATION:** Describe the theory of location for acceptance of this monument. Include monument origin and associated uncertainty. The iron pipe was previously witnessed by the Monroe County Surveyor, Kevin Enright, on December 15th, 2005 and accepted by the Monroe County Surveyor Review Board on December 19, 2006. The 2006 Monument Record accepted the iron pipe per a plat by Doug Curry, Westbrook Downs Section 4 Part 3 (1989) recorded as Instrument Number 1989900210.IN. Other References on File: Charles D. Graham survey, Cowdi, Mitchell & Bardi Builders Boundary Survey (2018) on file at the Recorder's Office as 2018001651.IN, a Charles D. Graham plat, Dan Rarey Type "E" Administrative Subdivision (2018) on file at the Recorder's Office as 2018015158.IN and an Eric L. Deckard survey, Fleetwood Boundary/As-Built Survey (2022) on file at the Recorder's Office as 2022003915.IN. Historic research has not yet been performed to prove the validity of this monument.

#### **CERTIFICATION:**



OFFICE OF THE MONROE COUNTY SURVEYOR • Trohn Enright-Randolph 119 W 7th Street, Bloomington, IN 47404 • 812-349-2570 • surveyorsoffice@co.monroe.in.us

Page 2 of 2

## MONUMENT RECORD State of Indiana - County of Monroe

Section: 14 Township: 9 North

**Range:** 2 West

Corner ID: Rich S-13

9

**Monument Description & Remarks:** 1-1/4" Iron Pipe found. Survey Sign 6ft above ground at pt. (D).

**References On File:** Raymond Graham survey, Westbrook Downs (1988); on file in Surveyor Office.

RECOVERY TIE DRAWING Field Book 37 Page No. 6 В **A** - 1-1/4" Iron Pipe. **B** - N 80° E 5.60' to Cable Tower. C - S 89° E 30.02' to 5/8" Rebar. **D** - S 45° E 18.07' to MAG nail Not To Scale in Survey Sign on 11" PWP. **Compass Bearing Magnetic North** 

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 3(2)-12-11 of the Indiana Code; and the above data is given under my hand and seal this 15th day of December 2005.

Administered by the Monroe County Surveyor 

Date: 9-19-06

